


Tapping Screws (Type A, AB, B)




Type A point:

A thread forming screw for use in thin metal .015 to .050 thick. Used with drilled, punched or nested holes in sheet metal, resin impregnated plywood, asbestos combinations, among others. Not recommended for new design.



Type AB point:


A thread forming screw combining locating point of Type A with thread size and pitch of Type B. Normal limitations of type B apply.



Type B point:

A thread forming screw for use in heavy metal. .050 to .200 thick. Larger root diameter with finer thread pitch for light and heavy sheet metal non - ferrous castings, plastics, impregnated plywoods, asbestos combinations, and other materials.

Thread Cutting Screws (Type 1, 17, 23, 25,)




Type 1 point:

A thread cutting screw with single flute for general use. Produces a fine standard machine screw thread for field replacement.



Type 17 point:

A thread cutting screw for wood with a coarse tapping screw thread and a special long sharp point fluted to capture chips.



Type 23 point:

A thread cutting screw in the fine thread series offering maximum thread cutting area and excellent chip clearing, with minimum tightening torques.



Type 25 point:

A thread cutting screw similar to type 23 point except with coarse Type B thread. For plastics and other soft ma-terials with large chip clearing and cutting edges.







